








Diagram illustrating assembly instructions and safety warnings:



- Warning 1:** A warning triangle with an exclamation mark is shown next to a box containing an L-shaped bracket and a crossed-out power drill icon, indicating that a power drill should not be used for this step.
- Warning 2:** A second warning triangle with an exclamation mark is shown next to a box containing a rectangular block and a crossed-out icon of a block being cut, indicating that the block should not be cut.
- Time:** A clock icon is shown next to the text "15'", indicating a 15-minute assembly time.
- Person:** An icon of a person is shown next to the number "1", indicating that one person is required for this step.

<p style="text-align: center;">A</p>  <p style="text-align: center;">x 1</p>	<p style="text-align: center;">B</p>  <p style="text-align: center;">x 3</p>	<p style="text-align: center;">C</p>  <p style="text-align: center;">M8 x 40</p> <p style="text-align: center;">x 6</p>	<p style="text-align: center;">D</p>  <p style="text-align: center;">x 6</p>	<p style="text-align: center;">E</p>  <p style="text-align: center;">x 1</p>
---	---	--	---	---






A



B x 3



1

<p>A</p>  <p>x 1</p>	<p>B</p>  <p>x 3</p>	<p>C</p>  <p>M8 x 40</p> <p>x 6</p>	<p>D</p>  <p>x 6</p>	<p>E</p>  <p>x 1</p>
---	---	--	---	---

