


Diagram illustrating assembly instructions and safety warnings:

- Warning 1:** A triangle with an exclamation mark points to a box containing:
 - An icon of an L-shaped metal bracket.
 - An icon of a power drill with a slash through it, indicating that a power drill should not be used.
- Warning 2:** A triangle with an exclamation mark points to a box containing:
 - An icon of a rectangular block being placed on a surface with a dashed line indicating the correct placement.
 - An icon of a rectangular block with a slash through it, indicating that the block should not be placed on its side.
- Time:** A clock icon with the text "10'" below it, indicating a 10-minute assembly time.
- Person:** An icon of a person with the text "1" below it, indicating that one person is required for assembly.




A

x 1

B





x 4



A


B x 4



**M6
x
20**

x 12

D



x 1

1

