












Warning icons and assembly instructions:


- Top Warning:** A triangle with an exclamation mark. To its left, a box contains an Allen key and a crossed-out power drill. To its right, a clock icon is labeled "30'".
- Bottom Warning:** A triangle with an exclamation mark. To its left, a box contains a rectangular block on a textured surface and a crossed-out block with a diagonal line. To its right, a person icon is labeled "1".

A  x 1	B  x 1	C1  x 1	C2  x 1	D  x 5
---	---	--	---	---




E  x 1	F  x 1	G  x 1	H  x 1	I  x 1
---	---	---	--	---

J




x 1

K



x 1

L




x 1

M




x 1

N



x 1

O



M8
x
10

x 6


P



M5
x
8

x 6


Q



M8
x
25

x 10

R



x 1


1

E





x 1

D



x 5




2

M






x 1





N







x 1







3







4





5



6



7




8

G




x 1


H



x 1



1a



1b

