










MALUNG





 <p>A line drawing of a power drill with a diagonal slash through it, indicating that power tools should not be used.</p>	 <p>A warning triangle containing an exclamation mark.</p>	 <p>A clock face icon.</p>
 <p>Two icons: a screwdriver on the left and a screwdriver with a diagonal slash through it on the right, indicating that screwdrivers should not be used.</p>	 <p>A warning triangle containing an exclamation mark.</p>	 <p>A simple line drawing of a person.</p>
		<p>20'</p>
		<p>2</p>


A



B x 4




A



x 1


B



x 4

1

A



x 1

B



x 4

A

