




Diagram illustrating assembly instructions and safety warnings:

- Top Section:** A box containing icons for a screwdriver and an Allen key, and a crossed-out power drill icon. To the right is a warning triangle with an exclamation mark. Further right is a clock icon with the text "30'" below it.
- Bottom Section:** A box containing icons for a block of material being placed on a surface and a block being cut. To the right is a warning triangle with an exclamation mark. Further right is a person icon with the number "1" below it.

1/4




A




x 8

B




x 1

C




x 1

D




x 1

E




x 8

F



x 1

G




x 2

H




x 2

I




x 2

J






x 1

K








x 1

!




1




2

2




x 2

A




x 8

B




x 1


E




x 8




1a






1b








1c



3




4



5

J



x 1

