











Diagram illustrating assembly steps and safety warnings:

- Step 1:** Shows an L-shaped metal bracket being secured with a power drill. A warning triangle with an exclamation mark is present.
- Step 2:** Shows a rectangular panel being placed on a surface. A warning triangle with an exclamation mark is present.
- Time:** A clock icon indicates a duration of 30' (30 minutes).
- Personnel:** A person icon indicates that 1 person is required for the task.



1



2

