



# SILERTON





An icon showing an L-shaped metal bracket inside a circle, next to a power drill with a diagonal line through it, indicating that a power drill should not be used for this step.	A warning triangle icon with an exclamation mark inside.	A clock icon representing a time requirement.
An icon showing a rectangular block on a surface with a hatched pattern, next to a similar block with a screw being inserted, crossed out with a diagonal line, indicating that a screw should not be used.	A warning triangle icon with an exclamation mark inside.	An icon of a person, representing the number of people required for the step.
		<b>15'</b>
		<b>1</b>




D x 4



A	B	C	D	E
		<p>M6 x 35</p>		
x 1	x 1	x 4	x 4	x 1

1



2

