












Diagram illustrating safety instructions for assembly:

- Top Section:** A box containing an Allen key icon and a crossed-out power drill icon, with a warning triangle above it. To the right is a clock icon with the text "15'" below it.
- Bottom Section:** A box containing an icon of a rectangular block on a textured surface and a crossed-out icon of a block with a hole, with a warning triangle above it. To the right is a person icon with the text "1" below it.


1/5

<p><b>A</b></p>  <p><b>x 1</b></p>	<p><b>B</b></p>  <p><b>x 1</b></p>	<p><b>C</b></p>  <p><b>x 2</b></p>	<p><b>D</b></p>  <p><b>M8 x 60</b></p> <p><b>x 1</b></p>
---	---	---	---













<p><b>E</b></p>  <p><b>M8 x 80</b></p> <p><b>x 8</b></p>	<p><b>F</b></p>  <p><b>Ø60</b></p> <p><b>x 1</b></p>	<p><b>G</b></p>  <p><b>Ø80</b></p> <p><b>x 8</b></p>	<p><b>H</b></p>  <p><b>x 1</b></p>
---	---	--	---

!



1

<b>A</b>  x 1	<b>B</b>  x 1	<b>F</b>  x 1	<b>G</b>  x 4	<b>D</b>  x 1	<b>E</b>  x 4	<b>H</b>  x 1
--	--	--	--	---	--	--




2

C




x 2

G




x 4

E





x 4

H




x 1






3

H



x 1



!

