


KUMALI








Diagram illustrating assembly instructions and warnings:

- Warning 1:** A box containing a crossed-out power drill icon and a warning triangle with an exclamation mark.
- Warning 2:** A box containing a crossed-out icon of a block being placed on a surface and a warning triangle with an exclamation mark.
- Time:** A clock icon with the text "10'" below it.
- Person:** An icon of a person with the text "1" below it.


A



B




A




x 1

B



x 1

1



2

