













A		4*30	54
B		M6*40	18
C			2
D		Φ8*30	16
E		Φ7*60	4
F		M6*60	6
G		M6*60	24
H			1




STEP:1







STEP:2

D		Φ8*30	4
G		M6*60	8






STEP:3

D		Φ8*30	4
E		Φ7*60	4
G		M6*60	8



STEP:4

B		M6*40	18
F		M6*60	6



STEP:5

A		4*30	52
---	---	------	----

