


# АБАСКА










Diagram illustrating assembly instructions and safety warnings:

- Warning 1:** A warning triangle with an exclamation mark is shown next to a box containing an Allen key and a power drill with a diagonal line through it, indicating that a power drill should not be used.
- Warning 2:** A second warning triangle with an exclamation mark is shown next to a box containing a rectangular block being placed on a surface and another block being lifted, indicating a lifting or placement instruction.
- Time:** A clock icon is shown next to the text "20'", indicating an estimated assembly time of 20 minutes.
- Personnel:** An icon of a person is shown next to the number "2", indicating that two people are required for assembly.




H




x 1

I




x 1

J




x 2

K




x 14

L



x 2


M



x 1


1

F





x 1

G




x 1



2

A



x 1

B



x 1

L






x 2

M



x 1




3

K



x 8



4

C



x 1

D



x 1

E




x 1



K





x 6




5





6



7



8





!

