








An icon showing an L-shaped metal bracket inside a circle. To its right is a power drill with a diagonal line through it, indicating it should not be used.	A warning triangle containing an exclamation mark.	A simple clock face icon.
<p>10'</p>		
An icon showing a rectangular block on a mat with a diagonal line through it. To its right is a block with a nail being driven into it, also with a diagonal line through it, indicating this method should not be used.	A warning triangle containing an exclamation mark.	A simple icon of a person.
<p>1</p>		

A	B	C	D	E
			 M6 x 20	
x 1	x 4	x 4	x 16	x 1

A








B x 4



C x 4



1

<p>A</p>  <p>x 1</p>	<p>B</p>  <p>x 4</p>	<p>C</p>  <p>x 4</p>	<p>D</p>  <p>M6 x 20 x 16</p>	<p>E</p>  <p>x 1</p>
---	---	---	--	---

