








An L-shaped metal bracket is shown inside a circle. To its right is a power drill with a diagonal line through it, indicating it should not be used.	A warning triangle containing an exclamation mark.	A clock face showing approximately 1:50.
A mattress is shown inside a circle. To its right is a person icon with a diagonal line through it, indicating that two people should not be on the bed.	A warning triangle containing an exclamation mark.	60' 2




E




x 4

F




x 4

G




x 4

H




x 8

I




x 12

J




x 4

K




x 26

L




x 12

M




x 13

N




x 26

O




x 1

P




x 1

R




x 4

S






x 2

T






x 1






1 x 4





2












3

B  x 2	H  x 8	I  x 8	L  M8 x 30 x 8	O  x 1
--	--	--	--	--




4

I  x 4	J  x 4	O  x 1	P  x 1	R  M8 x 35 x 4	S  x 2	T  x 1
--	--	--	--	---	--	--





5

L




O




6 x 13


K



M



N



7 x 13

