






!  15'




This block contains a warning triangle with an exclamation mark, a circular icon showing a screwdriver, a crossed-out power drill icon, a clock face, and the number 15'.

!  1





This block contains a warning triangle with an exclamation mark, a circular icon showing a cushion on a chair seat, a crossed-out icon of a cushion being inserted into a chair seat, a human figure icon, and the number 1.



1




2




3

C



x1

D



x1

